

CERTIFICATE OF COMPLIANCE

Certificate Number 20191118-E343871
Report Reference E343871-20191107
Issue Date 2019-NOVEMBER-18

Issued to: TECNICAS EXPANSIVAS S L
CALLE SEGADOR 13
LOGRONO ES 26006

This certificate confirms that representative samples of POSITIONING DEVICES
See Addendum Page for Models

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.


Standard(s) for Safety: UL 62275 - Cable Management Systems- Cable Ties for Electrical Installations

Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>




CERTIFICATE OF COMPLIANCE

Certificate Number 20191118-E343871
Report Reference E343871-20191107
Issue Date 2019-NOVEMBER-18

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Models:

BN25080-j, BN25100-j, BN25140-j, BN25160-j, BN25200-j, BN36140-j, BN36200-j, BN36300-j, BN36370-j, BN48120-j, BN48160-j, BN48180-j, BN48200-j, BN48250-j, BN48290-j, BN48370-j, BN48430-j, BN76150-j, BN76200-j, BN76290-j, BN76370-j, BN76450-j, BN76540-j, BN88770-j, BB25080-j, BB25100-j, BB25140-j, BB25160-j, BB25200-j, BB36140-j, BB36200-j, BB36300-j, BB36370-j, BB48120-j, BB48160-j, BB48180-j, BB48200-j, BB48250-j, BB48290-j, BB48370-j, BB48430-j, BB76150-j, BB76200-j, BB76290-j, BB76370-j, BB76450-j, BB76540-j, BB88770-j, 5102050118-j, 5102050120-j, 5102050121-j, 5102050122-j, 5102050125-j, 5102050131-j, 5102050135-j, 5102050137-j, 5102050140-j, 5102050141-j, 5102050142-j, 5102050143-j, 5102050145-j, 5102050146-j, 5102050147-j, 5102050149-j, 5102050151-j, 5102050175-j, 5102050176-j, 5102050178-j, 5102050180-j, 5102050181-j, 5102050182-j, 5102050183-j, 5102050018-j, 5102050020-j, 5102050021-j, 5102050022-j, 5102050025-j, 5102050031-j, 5102050035-j, 5102050037-j, 5102050040-j, 5102050041-j, 5102050042-j, 5102050043-j, 5102050045-j, 5102050046-j, 5102050047-j, 5102050049-j, 5102050051-j, 5102050075-j, 5102050076-j, 5102050078-j, 5102050080-j, 5102050081-j, 5102050082-j, 5102050095-j,



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

